

| Angle tolerance              |     |        |         |          | Length tolerance             |       |       |       |        |         |       |
|------------------------------|-----|--------|---------|----------|------------------------------|-------|-------|-------|--------|---------|-------|
| Arm length                   | >10 | >10–50 | >50–120 | >120–400 | Section length               | >3    | >3–6  | >6–10 | >10–30 | >30–120 | >120  |
| Dimension without tolerance  | ±1° | ±30'   | ±20'    | ±10'     | Dimension without tolerance  | ±0,10 | ±0,15 | ±0,18 | ±0,25  | ±0,35   | ±0,75 |
| Toler. for approx. dimension | ±4° | ±2°    | ±1°     | ±30'     | Toler. for approx. dimension | ±0,50 | ±0,60 | ±0,75 | ±1,0   | ±1,7    | ±3,0  |

|       |              |     |
|-------|--------------|-----|
| $p.F$ | 1051-01-00   | 1pc |
| $p.M$ | 1051-02-00/A | 1pc |